

# WC-1

## Process Controller



### Add-On Weld Process Controller

The Thermal Arc **WC-1**, Controller allows a compact packaged micro-processor system to be added onto a Thermal Arc **Ultima-150™** or **WC-100B** Component plasma welding package to provide accurate, and repeatable parameter control over the entire welding system. The Controller provides a full-featured current Pulser to aid in controlling warpage, penetration and the weld puddle. The Sloper function is designed to permit the development of a complete sequence of operation for a specific welding job. Two programmable outputs are featured, one is used to control the Plasma power source and the second, controls a Cold Wire Feed Motor Drive Control. The Controller provides 32 user selectable weld schedules.

### WC-1 Add-On Microprocess Controller

#### Features:

- 32 Weld Schedules
- Program/Run key lock switch
- 8 status LED's
- 9 Optically isolated inputs
- 5 solid-state isolated relay outputs
- Easy Three button programming
- Large LCD back light Display View screen
- RS232 Port for Computer programming interface
- Controlled Weld Pulse Rate up to 500 Pulses/Sec



- Plasma Welding
- Plasma Brazing
- Plasma Overlaying

**WC-1 Weld Processor Controller for Ultima-150 or WC100B packages**

## Specifications Information:

### WC-1 Microprocessor

**Power Requirements:** 115/240 vac 50/ 60Hz @ 0.2kw

**Operating Temp:** 10 Degrees F to +140 Degrees F  
(-23C to +60C)

**Dimensions:**

**Height:** 5" (102mm)

**Width:** 9" (165mm)

**Depth:** 11"(280mm)

**Relay Outputs:** 115 VAC/VDC 1 amps normally open contact

**Switch Inputs:** 5 — 24 vdc @ 1.0 — 8.0 ma

**Analog Outputs:** 10vdc precision reference output. 10bit resolution (10mv resolution) Maximum output current 10ma. Output is short circuit protected.

**Encoder Input:** Pulse accumulator input 5.0vdc TTL level with 4.7K pull-up. Maximum input frequency 15khz.



## Ordering Information:

	Part No.		Part No.
WC-1 Process Controller	600279	<b>Cable Assemblies</b>	
		WC-1 to Ultima® 150 or WC100B (required)	9-4129

### Accessories

25" Remote Hand Pendant 600280

### WF-100 Cold Wire Feed

For Cold Wire Feed ordering details see the WF-100 catalog pages.



*Got Power...?*

WORLD HEADQUARTERS: 101 S. Hanley Road • St. Louis, MO 63105 • 314-721-5573 • FAX 314-746-2161

**THERMADYNE.**

**THERMAL ARC**

**U.S. CUSTOMER SERVICE: 2200 Corporate Drive • Troy, OH 45373  
800-255-5846 • FAX 800-332-0946**

### International Offices

**International Customer Service**  
Galesville, Ontario, Canada  
Ph: (1) 905-827-9777  
Fax: (1) 905-827-0707

**Thermadyne Canada**  
Galesville, Ontario Canada  
Ph: (1) 905-827-1111  
Fax: (1) 905-827-3648

**Thermadyne UK**  
Cherley, England  
Ph: (44) 1257-251755  
Fax: (44) 1257-224800

**Thermadyne Asia Sdn. Bhd.**  
Kuala Lumpur, Malaysia  
Ph: (603) 6082-2988  
Fax: (603) 6030-1095

**Cipewild Australia**  
Melbourne, Australia  
Ph: (61) 3-9474-7400  
Fax: (61) 3-9474-7510

**Unique Welding Alloys**  
Johannesburg, South Africa  
Ph: (27) 11-917-3600  
Fax: (27) 11-917-8580

**Thermadyne Victor Brazil**  
Rio de Janeiro, Brazil  
Ph: (55) 21-2-485-8900  
Fax: (55) 21-2-485-8735

**Thermadyne Middle East**  
Dubai, United Arab Emirates  
Ph: (971) 4-332-9090  
Fax: (971) 4-332-5494

**Thermadyne de Mexico**  
Mexico City, Mexico  
Ph: (52) 55-5696-7407  
Fax: (52) 55-5696-7757

**Thermadyne Japan**  
Osaka, Japan  
Ph: (81) 6-4809-8411  
Fax: (81) 6-4809-8412

**Thermadyne Europe**  
Milan, Italy  
Ph: (39) 039-204-0001  
Fax: (39) 039-204-9922